

“Haggie Hints”

by George Delorme

Issue 4, 2002 Addendum



Haggie North America - Meeting your hoisting needs!

George Delorme

Phone: 514-453-1283; Fax: 514-453-0631; Email: georgedelorme@sympatico.ca; Toll Free: 1-888-HAGGIE-9 (424-4439)

The Effects of a Tight Groove in a Headsheave (Including Plastic Inserts)

Addendum

Question:

Does the plastic inserts need to be re-machined over the life of one rope or is it normal to allow the rope to "bed in" and live with the groove it makes itself?

Response:

No, there is no need to re-machine a liner once a rope has settled down - approximately after 3 months. It is only a must to have the 10% clearance as a new rope is installed.